



0008

Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

April 14, 2000

Department of Environmental Quality
Division of Water Quality
288 North 1460 West
P.O. Box 144870
Salt Lake City, Utah 84114-4870

Attention: Mr. Michael Herkimer

Subject: April 2000, UPDES Compliance Report
March 2000, Monitoring Period
UPDES Permit No. UT0024759
Discharge Monitoring Report Forms
Sunnyside Cogeneration Facility, Sunnyside, Utah

Dear Mr. Herkimer:

This letter summarizes the UPDES-Permit field activities at the Sunnyside Cogeneration Facility during March 2000. Rusty Netz, the Environmental Coordinator for the facility, has physically inspected the permit outfalls in accordance with the UPDES permit guidelines.

There were no discharges during the March 2000, monitoring period. The completed Discharge Monitoring Report Forms (EPA No. 3320-1) are included in Attachment A. The Bio-Monitoring Reports are included in Attachment B. The Field Data Sheets are included in Attachment C.

If you have any questions concerning this report, please contact Rusty Netz at (435) 888-4476.

Sincerely,

Agent for
Sunnyside Cogeneration Associates

Randy Scott
Randy Scott
Plant Manager

RN/ta
Enclosures:

Attachment A: Monitoring Report Forms
Attachment B: Bio-Monitoring Reports
Attachment C: Field Data Sheets

cc: Ken Wyatt, Division of Oil, Gas and Mining
SCA Plant file
Rusty Netz, COSI

RECEIVED

APR 17 2000

DIVISION OF
OIL, GAS AND MINING

Sheila
ACT/007/035
Incoming
Bill
Tracking